


9C

CAUTION: PROTECT BALLS AND RACES FROM SAWDUST, DIRT, PAINT, ETC. SHOULD BEARING BECOME "ROUGH" FROM DIRTY RACES, FLUSH THOROUGHLY WITH HOT SOAPY WATER, RINSE, OVEN DRY AND RE-OIL.



PART STAMPED WITH TRIANGLE NAME STAMP

3	BALLS9	BALL	1
2	7107	PLAIN RACE	1
1	7108	LOCKING RACE	1
DET	PART NUMBER	DESCRIPTION	AMT
C	TRIANGLE MANUFACTURING CO. DSHKOSH, WI.		

NAME 9" LAZY SUSAN BRG. ASS'Y	
USED IN	DATE
DATE 01-24-90	PART NO.
DRAWN SP	
CHECKED	SCALE 1 / 1

FIT ///

PLATING ELECTRO GALV.

MATERIAL SPEC. DET.

ALL DIMS ±.020 UNLESS SPECIFIED

CHANGE LEVEL
F 108-15-07

9C